

6/8/2020 Update by Tova Plaut



# BABY POOL



# Skimmer Before





### Skimmer After



### Cracks

#### **Before Repairs**

Foundational Cracks along base of large pool was causing leakage and disrupting the integrity of the pool walls and floors.

Without immediate repair, the pool would have needed a full replacement in the near future.



### Foundational Crack


Additional foundational cracks in the Main Pool were found in the side walls. The crack shown in this picture after repairs was the most dangerous of the many cracks found. The integrity of the side wall was already severely damaged. Immediate repairs and reinforcement was necessary.



# Crack Repair in process

Kevlar stapes Specialized Epoxy and other materials were used to repair and reinforce concrete throughout the three pools.







### Main Pool

#### Repairs


Crack repairs on all sides and floor of pools were necessary. Additionally, bubbling of cement on floor of pool was cut out, repaired and filled.

# Baby Pool









### New Stairs

#### Repaired

Stairs in all 3 pools were repaired and brought to code.

No sharp edges, smooth, level.



### New stairs

Guppy Pool



# Beautifying our Pool

New water line tile added beauty and style New water line markers


- Meet DOH guidelines
- Easy to read
- Clean look



# Surfacing

Surfacing Anti microbial – reduces chemical costs Smooth anti slip surface: eliminates cuts and abrasions







# Texture and Design

Anti slip surface in shallow: reduces accidents and injuries

#### Lane Markers:

Large easy to see markers (in a straight line! No more crooked swimming © )

#### **Depth Markers:**

Highly Visible

Compliant with Regulations

#### Stair Markers:

Highly Visible Anti Slip

**Regulation Compliant** 

# Deck Repairs

Repair cracks and reinforce deck damaged by time, wear and tear and climate







### Deck and Tile

Old Coping and Tile Cracked and damaged Rough texture Sharp edges



# New Rounded Coping and Tile

Cracks repaired. Proper seal between tile and coping Smooth Rounded Edges

# New Anti Slip Deck Markers (complies with regulations)






# Baby Pool and Deck

#### Before



#### After



# Guppy Pool and Deck

#### Before




After



# Shark (Main) Pool

#### Before



#### After



# Enjoying the Pool





